

A. HENRY, RADIO RESTORATIONS

5-VALVE
S.M.O.
1940

CULL'S
96 TRAFALGAR ST.
PHONE 32 - NELSON

TECHNICAL INFORMATION

BULLETIN NO. 141 *Sept 1940*

(TYPE)

5-VALVE BROADCAST PACEMAKER
RECEIVER.

only
Model 5MO
1940 (see next page)



RECEIVER
MODEL 5MO

COLLIER & BEALE LTD.

16th Sept 1940

WELLINGTON

5V PACEMAKER RECEIVER MODEL 5110

SCHEMATIC DIAGRAM





Plate F4 (Construction?)


Mod: reduce excessive output voltage

*Note error in drawing
diode filter res. + cap omitted,
R3*



TUBE POSITIONS FOR MODEL 5MD

(19)



Rear